

## Smart, Mark

---

**From:** Jeffrey Slark <jslark@nycoa.com>  
**Sent:** Thursday, November 7, 2019 4:24 PM  
**To:** Larson, Stephanie; Hilton, Joy (Palmer)  
**Cc:** Robert Filteau  
**Subject:** NYCOA - Cooling Water pH (permit NH00000116)  
**Attachments:** ATT00001.txt  
  
**Categories:** EZ Record - Shared

Hello,

There were 2 recent instances of our non-contact cooling water pH readings outside of the permit range. We believe the reason for the low effluent pH is due to the low pH coming from the Merrimack River.

- 10/24/19
  - o Intake reading: 6.31 (duplicate 6.16)
  - o Effluent reading: 6.41 (duplicate 6.39)
- 10/31/19
  - o Intake reading: 6.24 (duplicate 6.17)
  - o Effluent reading: 6.31 (duplicate 6.36)

I apologize for the delayed notification. I will make sure our Maintenance folks, who perform the cooling water monitoring, will notify me immediately if this happens in the future.

Thank you,

**Jeff Slark**

EHS & Security Coordinator



**Nylon Corporation of America**

333 Sundial Ave.

Manchester, NH 03103

Phone: 603-627-5150 (x318)

Email: [jslark@nycoa.com](mailto:jslark@nycoa.com)